



## Corded Scanner Installation Test Sheet

### Test Barcode



### ADD AN ENTER KEY (CARRIAGE RETURN/LINE FEED)

To add an **ENTER** key after scanned data, scan all **THREE** bar codes below in numerical order.

**1**



SCAN OPTIONS

**2**



<DATA><SUFFIX>

**3**



ENTER